# USB cable User Installation Manual v1.0

For Windows win7

(Dec/2009)　J

1.Power on your computer and boot to Windows.

2.Locate the USB port of your computer and plug in the USB cable,and open Device Manager.
Windows will detect the new device　(USB-Serial Controller)

## 3.right clik USB-Serial controller→Update Driver Software


4.select Browse my computer for driver software

5.click Browse… ,select win7 driver


6.click Next

7. Windows will show a dialog box, select　Install this driver software anyway

8. install successfully

9. Verifying the Installation

You should see the Prolific USB-to-Serial Comm Port (COM *) device listing. This also means that Windows has assigned the device to COM * port.